

The Boeing Company  
P.O. Box 516  
St. Louis, MO 63166-0516  
(314) 232-0232 TELEX 44-857

REC'D

JAN 26 1999

RESP  
RCAP

22 January 1999  
464C-4622-JWH



Ms. JoAnn Heiman, Chief  
RCRA Permitting & Compliance Branch  
U.S. Environmental Protection Agency Region VII  
Air, RCRA and Toxics Division  
726 Minnesota Avenue  
Kansas City, Kansas 66101

Enclosure: Corrective Action Quarterly Progress Report-Fourth Quarter 1998

Dear Ms. Heiman:

The enclosed Quarterly Progress Report is submitted as required by Section XI. of the Corrective Action Conditions of the Hazardous Waste Management Facility Permit, Number MOD 000 818 963. Three copies of the report will also be submitted to the Missouri Department of Natural Resources as required under the terms of the permit.

Please contact me should you need additional information.

Sincerely,

A handwritten signature in cursive script that reads "Joe Haake".

Joseph W. Haake. Group Manager  
Environmental and Hazardous Materials Services  
Dept. 464C, Bldg. 220, Mailcode S221-1400  
(314) 232-6941



R00115807

RCRA RECORDS CENTER

## **Quarterly Progress Report for Fourth Quarter 1998**

### **Description of the work completed**

No RFI work has been conducted since the submittal of the draft report on June 18, 1998.

In October repair work was conducted on the industrial sewer line that drains the containment area for the spent sodium hydroxide above ground tanks located near SWMU 17. Approximately 75 cubic yards of soil was excavated from this area for disposal.

### **Summary of all findings**

Analytical results indicated that the excavated soil was not hazardous.

### **Summary of all problems or potential problems and actions taken to rectify problems**

None

### **Projected work for the next reporting period**

Complete a Final RFI Report based on MDNR comments and recommendations.

### **Instances of noncompliance with the corrective actions of the permit**

None

## **Quarterly Progress Report for Fourth Quarter 1998**

### **Description of the work completed**

No RFI work has been conducted since the submittal of the draft report on June 18, 1998.

In October repair work was conducted on the industrial sewer line that drains the containment area for the spent sodium hydroxide above ground tanks located near SWMU 17. Approximately 75 cubic yards of soil was excavated from this area for disposal.

### **Summary of all findings**

Analytical results indicated that the excavated soil was not hazardous.

### **Summary of all problems or potential problems and actions taken to rectify problems**

None

### **Projected work for the next reporting period**

Complete a Final RFI Report based on MDNR comments and recommendations.

### **Instances of noncompliance with the corrective actions of the permit**

None